

Stock no.:

W51415

350 SEK

Shipping price / Shipping time:

- / 1-3 days

H&K Bildemontering AB

Nykyrka Industriområde

59197 Motala

Tel.: 0141-219822

Fax:

www.hk-bildemontering.com



Part - Trailing link front

Stock no.:	Position:	Quality:	Fits fr./to m.y
W51415	Right front upper	B	-
New code:	Manufacturer:	Manufacturer no.:	Original no.:
-	-	-	-
Description: DEFEKT DAMASK SE BILD			

Vehicle - Mercedes SL/SLC-Class

Chassi no.:	Model year:	Milage:	Fuel:
WDB1070451A005500	1984	15.800	Bensin
Colour:	Colour code:	Interior:	Interior code:
VIT	-	SKINN	-
Gearbox:	Gearbox no.:	Gearbox ratio:	Group code:
AUTOMAT	722.312	2,47	-
Engine:	Engine code:	Manufacturing date:	Registration date:
3,8 V8	-	-	-
Description: 2DR CAB 380SLKALIFORNIEN IMPORT			



Direct link: <http://www.bildelsbasen.se/195-W51415.html>