

Stock no.:

W188849

470 SEK

Shipping price / Shipping time:

- / 1-3 days

Boets Bildemontering AB

Boet Sågen

59992 Ödeshög

Tel.: 0144-20040

Fax:

www.boetsbildemontering.se



Part - Airbag krocksensor

| | | | |
|--------------|---------------|-------------------|-----------------|
| Stock no.: | Position: | Quality: | Fits fr./to m.y |
| W188849 | | A | - |
| New code: | Manufacturer: | Manufacturer no.: | Original no.: |
| - | - | 5M0909606A | - |
| Description: | | | |
| - | | | |

Vehicle - VW Touran

| | | | |
|-----------------------------------|--------------|---------------------|--------------------|
| Chassi no.: | Model year: | Milage: | Fuel: |
| WVGZZZ1TZ9W032562 | 2009 | 12.014 | Diesel |
| Colour: | Colour code: | Interior: | Interior code: |
| MRÖD | LA3T | TYG | AE |
| Gearbox: | Gearbox no.: | Gearbox ratio: | Group code: |
| 6VXL | KXD | - | - |
| Engine: | Engine code: | Manufacturing date: | Registration date: |
| 1,9TDi | BLS | 200808 | 20080926 |
| Description: | | | |
| TOURAN 1,9TDI 6VXL 5DR BUS DIESEL | | | |

Direct link: <http://www.bildelsbasen.se/118-W188849.html>