

Stock no.:

W5768

1.750 SEK

Shipping price / Shipping time:

- / 1-3 days

Svensk Bilåtervinning AB

Industrivägen 8

71531 Odensbacken

Tel.: 019-450690

Fax: 019-450692

www.svenskbilatervinning.se



Part - Window lifter electric complete

Stock no.:	Position:	Quality:	Fits fr./to m.y
W5768	Left front	A	-
New code:	Manufacturer:	Manufacturer no.:	Original no.:
	DENSO	AE062040-3610 DENSO	-

Description:

VÄNSTER FRAM KOMPL, TESTAD OK, 6 STIFT

Vehicle - Fiat Fullback

Chassi no.:	Model year:	Milage:	Fuel:
ZFAKVJY10G9001523	2016	4.679	Diesel
Colour:	Colour code:	Interior:	Interior code:
SVART	X08	SVART SKINN	46D
Gearbox:	Gearbox no.:	Gearbox ratio:	Group code:
AUT (AT5) 5 STEG	AUT (2700A391+3200A203)	3,912	-
Engine:	Engine code:	Manufacturing date:	Registration date:
2,4D (133KW)	4N15	201603	20160928

Description:

4DPICKUP2,4D 4WD AUT ABSESP GPS BACKKAMERA



Direct link: <http://www.bildelsbasen.se/170-W5768.html>