

Stock no.:

W570872

2.500 SEK

Shipping price / Shipping time:

- / 1-3 days

Vimmerby Bildemontering AB

Källenas 110

59872 Södra Vi

Tel.: 0492-20028

Fax: 0492-20720

www.vimmerbybildemontering.se



Part - Combined Instrument

Stock no.:	Position:	Quality:	Fits fr./to m.y
W570872		A	-
New code:	Manufacturer:	Manufacturer no.:	Original no.:
-	-	-	13355672
Description:			
Testad OK			

Vehicle - Opel Astra

Chassi no.:	Model year:	Milage:	Fuel:
W0LPF8EF9B8112047	2011	13.310	Diesel
Colour:	Colour code:	Interior:	Interior code:
VIT	-	-	-
Gearbox:	Gearbox no.:	Gearbox ratio:	Group code:
6vxl	-	-	-
Engine:	Engine code:	Manufacturing date:	Registration date:
1.7CDTi/A17DTR	-	201106	2011-06-28
Description:			
1.7CDTI DIESEL KOMBI 125HK 1.7CDTI/A17DTR 6VXL 5DR			



Direct link: <http://www.bildelsbasen.se/141-W570872.html>