

Stock no.:

W460892

100 SEK

Shipping price / Shipping time:

- / 1-3 days

Lycksele Bildemontering AB

Karossvägen 4

92145 Lycksele

Tel.: 0950-12140

Fax: 0950-14928

www.lyckselebildemontering.se



Part - Parkeringshjälp Frontsensor

Stock no.:	Position:	Quality:	Fits fr./to m.y
W460892	Front	A* A-detalj med nån defekt	-
New code:	Manufacturer:	Manufacturer no.:	Original no.:
	-	-	A66SX15K859-RA
Description:			
Fram			

Vehicle - Ford Kuga

Chassi no.:	Model year:	Milage:	Fuel:
WF0AXXWPMHJ77748	2017	930	Diesel
Colour:	Colour code:	Interior:	Interior code:
Vit	-	-	-
Gearbox:	Gearbox no.:	Gearbox ratio:	Group code:
Automat	A	-	-
Engine:	Engine code:	Manufacturing date:	Registration date:
1997	-	201701	20170113

Description:

FORD KUGA 13-16 AUTOMAT 5DR FORDON AVSETT FÖR FLER



Direct link: <http://www.bildelsbasen.se/140-W460892.html>