

Stock no.:

W580251

400 SEK

Shipping price / Shipping time:

- / 1-3 days

Vimmerby Bildemontering AB

Källenas 110

59872 Södra Vi

Tel.: 0492-20028

Fax: 0492-20720

www.vimmerbybildemontering.se



Part - Parkeringshjälp Frontsensor

Stock no.:	Position:	Quality:	Fits fr./to m.y
W580251		A	-
New code:	Manufacturer:	Manufacturer no.:	Original no.:
-	-	063023047965	0263023047
Description:			
Testad OK			

Vehicle - Honda CR-V

Chassi no.:	Model year:	Milage:	Fuel:
SHSRE6780EU011418	2014	26.765	Diesel
Colour:	Colour code:	Interior:	Interior code:
BLÅ	-	-	-
Gearbox:	Gearbox no.:	Gearbox ratio:	Group code:
6vxl	-	-	-
Engine:	Engine code:	Manufacturing date:	Registration date:
2.2CDTi/N22B4	-	-	2014-09-22
Description:			
2.2CDTI DIESEL SUV 150HK 2.2CDTI/N22B4 6VXL 5DR SUV			



Direct link: <http://www.bildelsbasen.se/141-W580251.html>