Stock no.:

W26153

250 SEK

Shipping price / Shipping time:

- / 1-3 days

Svensk Bilåtervinning AB

Industrivägen 8

71531 Odensbacken

Tel.: 019-450690

Fax: 019-450692

www.svenskbilatervinning.se

Part - Airbag krocksensor

Stock no.:	Position:	Quality:	Fits fr./to m.y
W26153		A -	-
New code:	**Manufacturer:**	**Manufacturer no.:**	**Original no.:**
	-	-	13504470

Description:

MONT I FRAMDÖRR, LIKSIDIG

Vehicle - Opel Astra

Chassi no.:	Model year:	Milage:	Fuel:
W0LBD8EC6G8106350	2016	5.423	Bensin
Colour:	**Colour code:**	**Interior:**	**Interior code:**
COOL BEIGE MET	GDC	SVART	TAQE
Gearbox:	**Gearbox no:**	**Gearbox ratio:**	**Group code:**
AUT (6 STEG) 6T35	MNU (95519804) 95524460	3,14	-
Engine:	**Engine code:**	**Manufacturing date:**	**Registration date:**
1,4T (110KW) LE2	B14XFT (12650830)95523654	201607	20161129

Description:

5DCBI 1,4T AUT ABS ESP2*PDC REGNSENSOR FÄRDDATO

Direct link: http://www.bildelsbasen.se/170-W26153.html