

Stock no.:

**W159945**

**150 SEK**

Shipping price / Shipping time:

- / 1-3 days

## Svensk Bilåtervinning AB

Industrivägen 8

71531 Odensbacken

Tel.: 019-450690

Fax: 019-450692

[www.svenskbilatervinning.se](http://www.svenskbilatervinning.se)



### Part - Washer pump Windshield

|            |               |                   |                 |
|------------|---------------|-------------------|-----------------|
| Stock no.: | Position:     | Quality:          | Fits fr./to m.y |
| W159945    |               | A                 | -               |
| New code:  | Manufacturer: | Manufacturer no.: | Original no.:   |
|            | -             | 430036418         | 13349273        |

Description:

VINDRUTA+BAKRUTA, TESTAD OK, 2 STIFT

### Vehicle - Opel Astra

|                   |                           |                     |                    |
|-------------------|---------------------------|---------------------|--------------------|
| Chassi no.:       | Model year:               | Milage:             | Fuel:              |
| W0LBD8EC6G8106350 | 2016                      | 5.423               | Bensin             |
| Colour:           | Colour code:              | Interior:           | Interior code:     |
| COOL BEIGE MET    | GDC                       | SVART               | TAQE               |
| Gearbox:          | Gearbox no.:              | Gearbox ratio:      | Group code:        |
| AUT (6 STEG) 6T35 | MNU (95519804) 95524460   | 3,14                | -                  |
| Engine:           | Engine code:              | Manufacturing date: | Registration date: |
| 1,4T (110KW) LE2  | B14XFT (12650830)95523654 | 201607              | 20161129           |

Description:

5DCBI 1,4T AUT ABS ESP2\*PDC REGSENSOR FÄRDDATO



Direct link: <http://www.bildelsbasen.se/170-W159945.html>