

Stock no.:

**W12376**

**798 SEK**

Shipping price / Shipping time:

- / 1-3 days

## Strängnäs Bilskrot AB

Malmbyvägen 7

64547 Strängnäs

Tel.: 0152-25500

Fax:

[strangnasbilskrot.se](http://strangnasbilskrot.se)



### Part - Drive shaft

Stock no.:

W12376

Position:

Right rear

Quality:

A  
OK

Fits fr./to m.y

-

New code:

Manufacturer:

-

Manufacturer no.:

-

Original no.:

33 21 7 553 562

Description:

Höger Bak

### Vehicle - BMW 3-Series

Chassi no.:

WBAVA51090KV25266

Model year:

2005

Milage:

18.500

Fuel:

-

Colour:

GRÅ

Colour code:

SPARKLING

Interior:

-

Interior code:

-

Gearbox:

MENUAL

Gearbox no.:

23007626305

Gearbox ratio:

-

Group code:

-

Engine:

2.0I BENSIN

Engine code:

N46B20B

Manufacturing date:

-

Registration date:

-

Description:

BMW 318I LIM 2.0I BENSIN MANUAL



Direct link: <http://www.bildelsbasen.se/439-W12376.html>