

Stock no.:

W228288

390 SEK

Shipping price / Shipping time:

- / 1-3 days

Svensk Bilåtervinning AB

Industrivägen 8

71531 Odensbacken

Tel.: 019-450690

Fax: 019-450692

www.svenskbilatervinning.se



Part - Rear sensor

Stock no.:	Position:	Quality:	Fits fr./to m.y
W228288		A	-
New code:	Manufacturer:	Manufacturer no.:	Original no.:
	-	-	LR038084
Description:			
INRE, TESTAD OK			

Vehicle - LandRover Range Rover

Chassi no.:	Model year:	Milage:	Fuel:
SALWA2KF7FA528778	2015	10.056	Diesel
Colour:	Colour code:	Interior:	Interior code:
FUJI WHITE	LRC867	SVART SKINN	-
Gearbox:	Gearbox no.:	Gearbox ratio:	Group code:
AUTOMAT 8-STEG	ZF8HP70	-	-
Engine:	Engine code:	Manufacturing date:	Registration date:
3,0 D 190KW	306DT	-	20150423
Description:			
5DSUV 3,0D AUT VIT L494 DYNAMIC			



Direct link: <http://www.bildelsbasen.se/170-W228288.html>