

Stock no.:

W11123

500 SEK

Shipping price / Shipping time:

- / 1-3 days

Mariestads Bildmontering och Återvinningsteknik AB

Förrådgatan 29

54235 Mariestad

Tel.: 0501-19250

Fax:

bildmonteringenimariestad.fbt.se



Part - Airbag krocksensor

Stock no.:	Position:	Quality:	Fits fr./to m.y
W11123		A	-
New code:	Manufacturer:	Manufacturer no.:	Original no.:
-	-	1T0 909 606 A	1T0909606A
Description:			
I Dörr alla lika. 1T0 909 606 A			

Vehicle - Skoda Fabia

Chassi no.:	Model year:	Milage:	Fuel:
TMBJH65J293028363	2008	9.392	Bensin
Colour:	Colour code:	Interior:	Interior code:
BLÅ	8D / F5Q	-	-
Gearbox:	Gearbox no.:	Gearbox ratio:	Group code:
MANUELL 5VLX	JUS	-	-
Engine:	Engine code:	Manufacturing date:	Registration date:
1,2	BZG	-	-
Description:			
4D,1,2,MAN,ABS,AC,CC21.06.2008 TILLVERKAD			



Direct link: <http://www.bildelsbasen.se/98-W11123.html>