

Stock no.:

W592833

800 SEK

Shipping price / Shipping time:

- / 1-3 days

Vimmerby Bildemontering AB

Källnäs 110

59872 Södra Vi

Tel.: 0492-20028

Fax: 0492-20720

www.vimmerbybildemontering.se




Part - Combined Instrument

Stock no.:	Position:	Quality:	Fits fr./to m.y
W592833		A	-
New code:	Manufacturer:	Manufacturer no.:	Original no.:
-	-	-	838000H043A
Description:			
Testad OK			

Vehicle - Citroen C1

Chassi no.:	Model year:	Milage:	Fuel:
VF7PNCFAC89316745	2009	3.602	Bensin
Colour:	Colour code:	Interior:	Interior code:
RÖD	-	-	-
Gearbox:	Gearbox no.:	Gearbox ratio:	Group code:
5vxl	-	-	-
Engine:	Engine code:	Manufacturing date:	Registration date:
1.0i/CFA	-	200902	2009-02-23
Description:			
1.0I KOMBI-SEDAN 68HK 1.0I/CFA 5VXL 5DR CC BENSIN			



Direct link: <http://www.bildelsbasen.se/141-W592833.html>