

Stock no.:

W599729

625 SEK

Shipping price / Shipping time:

- / 1-3 days

Vimmerby Bildemontering AB

Källnäs 110

59872 Södra Vi

Tel.: 0492-20028

Fax: 0492-20720

www.vimmerbybildemontering.se



Part - Drive shaft

Stock no.:	Position:	Quality:	Fits fr./to m.y
W599729	Right front	A	-
New code:	Manufacturer:	Manufacturer no.:	Original no.:
-	-	-	-
Description:			
Testad OK			

Vehicle - Peugeot 107

Chassi no.:	Model year:	Milage:	Fuel:
VF3PNCFB0DR057842	2013	7.100	Bensin
Colour:	Colour code:	Interior:	Interior code:
SVART	-	-	-
Gearbox:	Gearbox no.:	Gearbox ratio:	Group code:
AUTOMAT	-	-	-
Engine:	Engine code:	Manufacturing date:	Registration date:
1.0i/CFB	-	201305	2013-05-24
Description:			
1.0I KOMBI-SEDAN 68HK 1.0I/CFB AUTOMAT 5DR CC BENSI			

Direct link: <http://www.bildelsbasen.se/141-W599729.html>