

Stock no.:

W607881

Pris saknas

Shipping price / Shipping time:

- / -

Vimmerby Bildemontering AB

Källenas 110

59872 Södra Vi

Tel.: 0492-20028

Fax: 0492-20720

www.vimmerbybildemontering.se



Part - Kylfläktsmotstånd

Stock no.:	Position:	Quality:	Fits fr./to m.y
W607881		A	-
New code:	Manufacturer:	Manufacturer no.:	Original no.:
-	-	-	9652021180
Description:			
Testad OK!			

Vehicle - Peugeot Partner

Chassi no.:	Model year:	Milage:	Fuel:
VF37FBHY6GJ891377	2017	6.145	Diesel
Colour:	Colour code:	Interior:	Interior code:
VIT	-	-	-
Gearbox:	Gearbox no.:	Gearbox ratio:	Group code:
5vxl	-	-	-
Engine:	Engine code:	Manufacturing date:	Registration date:
1.6HDI/BHY	-	201611	20161124
Description:			
1.6HDI DIESEL SKÅP 99HK 1.6HDI/BHY 5VXL 5DR SKP DIE			



Direct link: <http://www.bildelsbasen.se/141-W607881.html>