

Stock no.:

**W636362**

# Pris saknas

Shipping price / Shipping time:

- / -

## Vimmerby Bildemontering AB

Källenas 110

59872 Södra Vi

Tel.: 0492-20028

Fax: 0492-20720

[www.vimmerbybildemontering.se](http://www.vimmerbybildemontering.se)



### Part - Rear sensor

Stock no.:	Position:	Quality:	Fits fr./to m.y
W636362		A	-
New code:	Manufacturer:	Manufacturer no.:	Original no.:
-	-	-	-
Description:			
Testad OK!			

### Vehicle - Seat Arona

Chassi no.:	Model year:	Milage:	Fuel:
VSSZZKJZLR202776	2020	-	CNG
Colour:	Colour code:	Interior:	Interior code:
VIT	-	-	-
Gearbox:	Gearbox no.:	Gearbox ratio:	Group code:
5vxl	-	-	-
Engine:	Engine code:	Manufacturing date:	Registration date:
1.0TGi/DBYA	-	202007	20200824
Description:			
1.0TGI CROSSOVER 90HK 1.0TGI/DBYA 5VXL CC CNG			

Direct link: <http://www.bildelsbasen.se/141-W636362.html>