

Stock no.:

W636366

375 SEK

Shipping price / Shipping time:

- / 1-3 days

Vimmerby Bildemontering AB

Källnäs 110

59872 Södra Vi

Tel.: 0492-20028

Fax: 0492-20720

www.vimmerbybildemontering.se



Part - Rear sensor

Stock no.:	Position:	Quality:	Fits fr./to m.y
W636366	-	A	-
New code:	Manufacturer:	Manufacturer no.:	Original no.:
-	-	-	-
Description:			
Testad OK			

Vehicle - Seat Arona

Chassi no.:	Model year:	Milage:	Fuel:
VSSZZKJZLR202776	2020	-	-
Colour:	Colour code:	Interior:	Interior code:
VIT	-	-	-
Gearbox:	Gearbox no.:	Gearbox ratio:	Group code:
5vxl	-	-	-
Engine:	Engine code:	Manufacturing date:	Registration date:
1.0TGi/DBYA	-	202007	2020-08-24
Description:			
1.0TGI CROSSOVER 90HK 1.0TGI/DBYA 5VXL CC CNG			



Direct link: <http://www.bildelsbasen.se/141-W636366.html>