

Stock no.:

W636752

300 SEK

Shipping price / Shipping time:

- / 1-3 days

Vimmerby Bildemontering AB

Källenas 110

59872 Södra Vi

Tel.: 0492-20028

Fax: 0492-20720

www.vimmerbybildemontering.se



Part - Rear sensor

Stock no.:	Position:	Quality:	Fits fr./to m.y
W636752		A	-
New code:	Manufacturer:	Manufacturer no.:	Original no.:
-	-	0263003991	-
Description:			
Testad Ok			

Vehicle - BMW 1-Series

Chassi no.:	Model year:	Milage:	Fuel:
WBAUD71050P443147	2011	14.000	Diesel
Colour:	Colour code:	Interior:	Interior code:
SVART	-	-	-
Gearbox:	Gearbox no.:	Gearbox ratio:	Group code:
6vxl	-	-	-
Engine:	Engine code:	Manufacturing date:	Registration date:
2.0D//N47D20C	-	201010	2010-10-19
Description:			
118 2.0D CC 143HK 2.0D//N47D20C 6VXL 5DR CC DIESEL			



Direct link: <http://www.bildelsbasen.se/141-W636752.html>