

Stock no.:

W724430

Pris saknas

Shipping price / Shipping time:

- / 1-3 days

Vimmerby Bildemontering AB

Källenas 110

59872 Södra Vi

Tel.: 0492-20028

Fax: 0492-20720

www.vimmerbybildemontering.se



Part - Lambda probe

Stock no.:	Position:	Quality:	Fits fr./to m.y
W724430		A	-
New code:	Manufacturer:	Manufacturer no.:	Original no.:
-	-	-	-
Description:			
Främre Testad OK Främre			

Vehicle - Seat Arona

Chassi no.:	Model year:	Milage:	Fuel:
VSSZZKJZKR110071	2019	13.503	Bensin
Colour:	Colour code:	Interior:	Interior code:
VIT	-	-	-
Gearbox:	Gearbox no.:	Gearbox ratio:	Group code:
5vxl	-	-	-
Engine:	Engine code:	Manufacturing date:	Registration date:
1.0/DKLA	-	201902	2019-03-19
Description:			
1.0 TSI CROSSOVER 95HK 1.0/DKLA 5VXL 5DR SUV BENSIN			



Direct link: <http://www.bildelsbasen.se/141-W724430.html>